

WLD 141
Flux Cored Arc Welding I
(Gas Shielded)



Index

Course Information	3
Accessing ebook and CourseMate info.	4
Information Sheets	5-8
Craftsmanship Expectations for Welding Projects	9
Welding Projects	10-33
Final Exam	34-37
Assessment Breakdown for Course	38



This project was supported, in part,
by the
National Science Foundation
Opinions expressed are those of the authors
And not necessarily those of the Foundation

Course Assignments

Required Text Book

Welding Principles and Applications 7th edition by Larry Jeffus,
Chapter 12, Flux Cored Arc Welding Equipment, Setup, and Operation
Chapter 26, Weldability of Metals

Math

Practical Problems in Mathematics 6th edition by Robert Chasan
Chapter 28, Volume of Cubes and Rectangular Shapes
Chapter 29, Volume of Rectangular Containers
Chapter 30, Circumference of Circles, and Perimeter of Semicircular-Shaped Figures
Chapter 31, Area of Circular and Semicircular Figures
Chapter 32, Volume of Cylindrical Shapes

Recommended assignments

Complete review question following each assigned chapter

Quizzes

Complete Interactive Quiz in CourseMate for each assigned chapter

Reference List

- **The Procedures Handbook of Arc Welding** by Lincoln Electric
- **IPT's Metal Trades Handbook** (Revised Edition-1993) by Ronald G. Garby and Bruce J. Ashton
- **Gas Metal Arc Welding Handbook** by William H. Minnick
- **D1.1 Structural Steel Code Book** by the American Welding Society

Video Training

View the DELMAR FCAW VIDEOS before starting this course work. They are Located in the classroom 132/a.

Timeline

The Welding Department's Open-entry, open-exit instructional format allows the students to work at their own pace. It is the student's responsibility to complete all assignments in a timely manner. See your instructor if you need assistance.

Outcome Assessment Policy

The student will be assessed on his/her ability to demonstrate the development of course outcomes. The methods of assessment may include one or more of the following: Oral or written examinations, quizzes, written assignments, visual inspection techniques, welding tests, safe work habits, task performance and work relations.

Accessing the Interactive ebook for Principles and Applications and Practical Problems in Mathematics

Here is a link to the publishers website that goes over some “getting started” procedures with CourseMate.

<http://www.cengage.com/tlconnect/client/product/fcis.do?productId=535>

For New Students

Your book bundle will contain an access code for both your Principles and Applications book and the Practical Problems in Mathematics.

For Returning Students

If you have the Seventh Edition of the Principles and Applications book you should have an access code. If not see your instructor. For the math book you will have to go to this site <http://www.cengagebrain.com/shop/isbn/9781111313593> and rent the ebook for either a six month or one year option.

Your math quizzes will be accessible through Desire 2 Learn. Your Instructor will assist you in accessing this.

Course Key There will be a master course key containing all of the courses available on CourseMate. You will find the course you are currently taking and enter the corresponding number in the appropriate area in CourseMate.

Note For each class there will be separate Access code and course key for Principles and Applications and Practical Problems in Mathematics

Equipment for Shielded Flux Cored Welding Process

Power Sources


The flux-core process utilizes the same basic equipment as any of the other gas metal arc welding processes that incorporates a power source, wire drive-control, gun, and a system for supplying a shielding gas.

A constant voltage type power source is required to obtain the maximum efficiency from the flux-core process. This type of power source automatically supplies the correct amperage to maintain constant arc voltage.

Since most constant voltage welding machines are rated for 100% duty cycle at rated current, they provide power for automatic and semi-automatic welding equipment. This factor provides a safety margin when the welding machines are operated for short periods of time at currents above their rated capacity.

An outstanding advantage provided by constant voltage welding machines is the simplicity of welding operation. The electrode feed speed is adjusted to give the desired welding amperage that is automatically provided by the constant voltage-welding machine.

Electrode Feed Controls




Wire

The purpose of the electrode feed control is to supply the continuous electrode (wire) to the welding arc at a preset rate. The electrode feed speed controls the welding amperage from the constant voltage

power source. Flux-core electrodes used in the process require V-grooved feed rolls of correct size so that the electrodes are not flattened or distorted.

Welding Guns

Welding guns used in the flux-core process serve the purpose of providing transfer of the welding current to the electrode, shielding gas coverage, and control of the arc. The guns may be air cooled or water cooled depending upon the service conditions. Contact tips are subject to wear and should be changed periodically to insure correct size and reliable current pickup. Inside diameter tolerance on the contact tip is important to assure reliability of the process.



Wire Conduit Installation

SINCE YOU WILL BE USING THE "TWECO MIG-GUNS" ON THE EQUIPMENT, IT IS ESSENTIAL THAT YOU BE ABLE TO REPLACE PARTS AS NEEDED, THE WIRE GUNS FROM MOST OTHER MANUFACTURERS ARE SIMILAR; BUT, IF DIFFICULTY IS ENCOUNTERED, YOU SHOULD READ THE APPROPRIATE INSTRUCTION SHEET.

Installing a New Wire Conduit in Tweco Mig Guns

The procedure for removal and installation of a wire conduit in either the No. 4 AN or No. 6 MIG GUN is identical. The No. 6 MIG GUN wire conduit stop has two O-ring gas seals. The No. 4 AN MIG GUN wire conduit stop has a sleeve type gas seal only. (See appropriate drawing.)

1. (See the appropriate drawings.) Be sure the MIG GUN is stretched in a straight line free from twists when removing or installing a wire conduit. To remove old wire conduit, first remove the MIG-GUN nozzle, contact tip, and nozzle insulator. No. 4 AN MIG GUNS have a sliding adjustable style nozzle (see drawing) and the No. 6 MIG GUN has a fixed threaded style nozzle (see drawing). Loosen the Allen screw in the Gas Diffuser (see drawings) and remove the Gas Diffuser. Loosen the Allen screw in the MIG KWIK Connector Plug (see drawings) and pull the old wire conduit out of the Cable hose at the MIG KWIK Connector end.
2. To install a new Wire Conduit Liner, first inspect the gas seal O-rings or sleeve type gas seal for cuts or damage. Start from the MIG KWIK Connector end of the assembly and begin pushing the conduit through the MIG KWIK Connector Plug, the Cable hose, and into the gun. If the conduit should lodge along the way, gently whip or work the Cable hose to aid forward movement.
3. When the wire conduit stop meets the end of the MIG KWIK Connector Plug (see pictures), the small Allen screw in the Connector Plug must be securely tightened onto the conduit to prevent its backward movement.



4. **IMPORTANT:** When the conduit is fully inserted into the Cable hose and the conduit stop is firmly against the Connector Plug, the "raw end" of the conduit will protrude out of the open end of the gun conductor tube (see picture). Cut the conduit end off squarely outside the conductor tube according to dimensions in (see picture). The cut end which seats in the Gas Diffuser must be filed and reamed perfectly smooth on the inside and outside radii so that the wire feed will not be obstructed.
5. Seat the smoothed end of the wire conduit into the end of the Gas Diffuser and screw the diffuser into the conductor tube. When the Gas Diffuser is fully tightened, remove the small Allen screw to make sure that the conduit is visible through the screw hole. This inspection will assure that the wire conduit is fully seated in the Gas Diffuser. Replace and securely tighten the Allen screw onto the wire conduit. **DO NOT OVERTIGHTEN CAUSING DISTORTION OF THE CONDUIT!**

Wire Conduit Installation

Craftsmanship Expectations for Welding Projects

The student should complete the following tasks prior to welding.

1. Thoroughly read each drawing.
2. Make a cutting list for each project. Cut at least two project assemblies of metal at a time. This will save a great amount of time.
3. Assemble the welding projects per drawing specifications.
4. Review the Welding Procedure portion of the prints to review welding parameter information.
5. See the instructor for the evaluation.

Factors for grading welding projects are based on the following criteria:

Metal Preparation

Oxyacetylene Cut quality
Grind all cut surfaces clean

Project Layout

Accurate (+/- 1/16")
Limit waste

Post Weld Clean-up

Remove Slag/Spatter
Remove sharp edges



Example of a High Quality Weld

Weld Quality per AWS D1.1

VT Criteria	Cover Pass
Reinforcement (groove welds)	Flush to 1/8"
Fillet Weld Size	See specification on drawing
Undercut	1/32" deep
Weld Contour	Smooth Transition
Penetration	N/A
Cracks	None Allowed
Arc Strikes	None Allowed
Fusion	Complete Fusion Required
Porosity	None Allowed
Overlap	None Allowed

E71T-1 Bead Plate

Project #1

Welding Sequence





E71T-1—Apply a new surface on the base metal by overlapping stringer beads. Alternate welding directions (i.e. right to left then left to right).



VT Criteria	Student Assessment	Instructor Assessment
Reinforcement		
Undercut		
Bead Contour		
Cracks		
Arc Strikes		
Fusion		
Porosity		
Bend Test		
		Grade Date

WLD 141
Bead Plate
Flat Position

- Welding Procedure
1. Electrode _____ E71T-1
 2. Diameter _____ 1/16"
 3. Polarity _____ DCRP
 4. Voltage _____ 24-26
 5. Amperage _____ 200-220
 6. Welding Position _____ Flat
 7. Material _____ 1/2" Plate
 8. Travel Angle (Drag) _____ 20°-30°
 9. Work Angle _____ Varies
 10. CO₂ Shielding gas _____ 45 cfh



Inch	MM
1/16"	1.6
1/8"	3.2
1/4"	6.4
1/2"	12.7
1"	25.4



Portland Community College
Welding Technology

Tolerance (Unless otherwise Specified)
Dimensional ± 1/16" Angle ± 5°

WLD 141-01

Drawn By: John Deering	Size:	Qc No.	Rev.
Chk By: TANNER SCOTT	Date: 8/18/08	Approve	Date
			Sheet

S.I. Conversion

Size (WxHxL)

Port No. Required

E71T-1 T-Joint (1F)


Project #2

Welding Sequence

E71T-1-- Root Pass Single pass technique with slight weave to ensure the weld metal is fusing into both pieces of metal.

E71T-1—Fill Use the split bead technique with stringer beads ensuring even fill.

E71T-1—Finish Beads Use stringer bead technique keeping the electrode in the puddle at all times.






VT Criteria	Student Assessment	Instructor Assessment
Reinforcement		
Undercut		
Bead Contour		
Cracks		
Arc Strikes		
Fusion		
Porosity		
Bend Test		
		Grade Date

WLD 141
Flat (1F)
T-Joint

Welding Procedure

1. Electrode _____ E71T-1
2. Diameter _____ 1/16"
3. Polarity _____ DCRP
4. Voltage _____ 24-28
5. Amperage _____ 180-230
6. Welding Position _____ Flat (1F)
7. Material _____ 1/2" Plate
8. Travel Angle (Drag) _____ 20°-30°
9. Stickout _____ 3/4"
10. C2 Shielding gas _____ 45 cfh



Inch	MM
1/16"	1.6
1/8"	3.2
1/4"	6.4
1/2"	12.7
1"	25.4

Part	No. Required	Size (WxHxL)	S.I. Conversion



Portland Community College
Welding Technology

Tolerance (Unless otherwise Specified)		WLD 141-02	
Dimensional ± 1/16" Angle ± 5°		Size:	Qc No.
Drawn By: John Deering		Approve	Date
Chk By: TANNER SCOTT		Date: 8/18/08	Sheet

E70T-1 T 3/32" Hog Wire -Joint (2F)

Project #3

Welding Sequence

E71T-1-- Root Pass

Single pass technique where the focus of the wire is on the bottom plate by one diameter's width. The weld metal will then "float" into the vertical plate.

E71T-1—Fill

Use the split bead technique with stringer beads ensuring even fill.

E71T-1—Finish Beads

Use stringer bead technique keeping the electrode in the puddle at all times.



The weld joint pictured above is what is known as a 2F or Horizontal Fillet Weld. Notice that the joint has been securely tacked at each end prior to starting the weld. Make sure your project is tacked on all four sides before you start to weld. If you do not tack your piece before you start welding or if your tacks are too small, the parts will pull or move while you are welding them. Begin the weld at one end of the joint and continue to weld at a constant even speed all of the way to the other end without stopping. After you finish the first root pass have your instructor check your work.

E70T-1 Dual Shield 3/32" wire (Hog Wire) Information

- Use big tacks where you are going to stop and start
- 5/16" is the largest fillet weld allowed per AWS D1.1
- "Double Pump" Stop to fill crater







Notice the desirable fillet weld profiles. Acceptable fillet weld profiles will have an equal amount of weld on each of the legs of the weld.

VT Criteria	Student Assessment	Instructor Assessment
Reinforcement		
Undercut		
Bead Contour		
Cracks		
Arc Strikes		
Fusion		
Porosity		
Bend Test		
		Grade Date

WLD 141
"Hog Wire"
T-Joint

Welding Procedure

1. Electrode _____ E71T-1
2. Diameter _____ 3/32"
3. Polarity _____ DCRP
4. Voltage _____ 27-29
5. Amperage _____ 400 - 460
6. Welding Position _____ Horizontal (2F)
7. CO₂ Shielding Gas _____ 45 cfh
8. Material _____ 1/2" Plate
9. Travel Angle (Drag) _____ 20°-30°
10. Stick Out _____ 3/4" to 1"



Inch	MM
1/16"	1.6
1/8"	3.2
1/4"	6.4
1/2"	12.7
1"	25.4

Part	No. Required	Size (WxHxL)	S.I. Conversion



Portland Community College

Welding Technology

Tolerance (Unless otherwise Specified)
Dimensional $\pm 1/16"$ Angle $\pm 5^\circ$

Drawn By:
Jonin Deering

WLD 141-03

Size: _____ Qc No. _____
Rev. _____

Date: 7/7/09

Chk By: TANNER SCOTT

Approve _____

Date _____

Sheet _____

E71T-1 T-Joint (3F)

Project #4

Welding Sequence

E71T-1-- Root Pass

Single pass technique with slight weave to ensure the weld metal is fusing into both pieces of metal.

E71T-1—Fill

Use the split bead technique with stringer beads ensuring even fill.

E71T-1—Finish Beads

Use stringer bead technique keeping the electrode in the puddle at all times.







The weld joint pictured above is in the 3F or Vertical position. This weld will be started from the bottom of the joint and weld to the top. It is important to remember while you are welding this type of a joint that one side of the weldment is the edge of the plate and the other side of the weldment is the center of the plate. The reason this is important is the edge of the piece being welded will be effected by the heat of the weld much sooner then the piece you are centered on.

Once you begin the weld watch for the puddle to form. When you see the puddle form and fill out into a circle begin to move upward slowly keeping the wire electrode in the center of the puddle. If you move to quickly and get ahead of the puddle the wire electrode will burn a hole in the metal.

VT Criteria	Student Assessment	Instructor Assessment
Reinforcement		
Undercut		
Bead Contour		
Cracks		
Arc Strikes		
Fusion		
Porosity		
Bend Test		
	Grade	Date

WLD 141
Vertical Fillet (3F)



- Welding Procedure
1. Electrode _____ E71T-1
 2. Diameter _____ 1/16"
 3. Polarity _____ DCRP
 4. Voltage _____ 24-26
 5. Amperage _____ 200-220
 6. Welding Position _____ Vertical (3F)
 7. CO₂ Shielding Gas _____ 45 cfh
 8. Material _____ 1/2" Plate
 9. Travel Angle _____ 20°-30°
 10. Work Angle _____ Varies

Inch	MM
1/16"	1.6
1/8"	3.2
1/4"	6.4
1/2"	12.7
1"	25.4

Part	No. Required	Size (WxHxL)	S.I. Conversion

Tolerance (Unless otherwise Specified)
Dimensional: ± 1/16" Angle ± 5°

Drawn By:
John Deering

Chk By: TANNER SCOTT



Portland Community College
Welding Technology

WLD 141-04

Size	Qc No.	Rev.

Approve

Date: 8/19/08

Date

Sheet

E71T-1 T-Joint (4F)

Project #5

Welding Sequence

E71T-1-- Root Pass

Single pass technique with slight weave to ensure the weld metal is fusing into both pieces of metal.

E71T-1—Fill

Use the split bead technique with stringer beads ensuring even fill.

E71T-1—Finish Beads

Use stringer bead technique keeping the electrode in the puddle at all times.







Pictured above is a weld project fixtured in the 4F or overhead position. Although the overhead position may seem like a difficult position to weld in, it is very similar to welding in the horizontal position. The force of the arc coming off of the end of the electrode actually helps to lay the weld down. It does help to work the gun up and down slightly when putting this weld in to facilitate positioning the weld equally into both sides of the root.

VT Criteria	Student Assessment	Instructor Assessment
Reinforcement		
Undercut		
Bead Contour		
Cracks		
Arc Strikes		
Fusion		
Porosity		
Bend Test		
		Grade Date

WLD 141
Overhead (4F)
T-Joint

Welding Procedure

1. Electrode _____ E71T-1
2. Diameter _____ 1/16"
3. Polarity _____ DCRP
4. Voltage _____ 24-26
5. Amperage _____ 200-220
6. Welding Position _____ Overhead (4F)
7. Material _____ 1/2" Plate
8. Travel Angle (Drag) _____ 20°-30°
9. Work Angle _____ Varies
10. CO Shielding gas _____ 45 cfh



Inch	MM
1/16"	1.6
1/8"	3.2
1/4"	6.4
1/2"	12.7
1"	25.4

S.I. Conversion

Size (WxHxL)

Port No. Required



Portland Community College

Welding Technology

Tolerance (Unless otherwise Specified)
Dimensional $\pm 1/16"$ Angle $\pm 5^\circ$

Drawn By: John Deering

Chk By: TANNER SCOTT


Date: 8/19/08

WLD 141-05

Size: Qc No. Rev.

Approve Date Sheet

Groove Welding Information Sheet



Acceptable butt weld or groove weld profile.

COMMENTARY ON TECHNIQUES WITH PICTORIAL ILLUSTRATIONS

The practicality of multipass welding will depend upon many factors in each individual application. Multipass welding is usually done with smaller beads deposited at lower heat inputs than would be employed in a single pass. This procedure is used when there is a need for rapid cooling in the heat affected zone and weld toughness which develops in a multipass weld deposit resulting from grain refinement and the tempering effect of stringer beads. The desirability of multipass welding and the finesse with which it must be applied is judged from the weldability of the steel and the toughness estimated to be required in the weld joint area. Small beads are more susceptible to stress cracking and cause more distortion than large beads. Stress cracking and distortion can be minimized by using procedures such as back stepping, alternating the stringer beads, etc.

The purpose of minimizing weaving motion is to obtain a reasonably fast travel speed and, thus, avoid an excessively high heat input. The maximum temperature attained and the length of time at temperature is not only dependent upon the welding process employed, but also the technique exercised

by the welder. Some fabricators insist on welding with high heat inputs in order to deposit larger beads and, thus, more quickly accomplish the welding of a particular joint.

The grains will be much coarser in a large, single-pass weld made at slow speed than in a thin single bead deposited at high speed. It is better to maintain preheat and interpass temperatures within recommended limits, and to use higher welding current and fast travel. Coarse-grains are undesirable because they lack ductility and impact strength. This effect is especially pronounced where each bead is the full width of the groove.



In the picture above slag and or gas was trapped because there was too little space between the sidewall and the bead or between beads. Undercut must be avoided with any of the beads because this can trap slag. The defects in this weld can be corrected by grinding or air arc gouging before proceeding with the welding.

Shop Pre-Test Bend Test Procedure for 1" Test Plate

Bend tests are used to determine the ductility and soundness of a weld joint. The test will determine if fusion was obtained in the weld joint. Use the following procedure in preparing and bending your coupons.

1. Reference the AWS D1.1 Structural Welding Code to determine the dimensional layout of the bend coupons (use this diagram for all positions).
2. Flush back up strip off of the plate. **Note: flushing of the backing strip maybe removed by flushing provided that at least 1/8 inch of its thickness is left to be removed by grinding.**
3. Layout four 3/8" thick coupons and cut using the track burner. **Do Not Bend coupons greater than 3/8" thick. This will damage the machine.**
4. Allow coupon to air cool. **Do Not Quench!**
5. Grind coupon's smooth, ensuring grinding marks are going with the length of the coupon's and all edges are rounded.
6. Request permission from your instructor to use the bend test machine.
7. **CAUTION: Keep hands and fingers clear when operating equipment.**
8. Ensure guard is in the correct position. The coupons sometimes eject out the end of the machine rapidly.
9. Place coupon in the machine taking care to not position your hands/fingers in the way. Locate weld in the center of the die. Position coupons for side bends only.
10. Actuate the machine by the lever on top of the machine and stand clear of end where the coupon will exit.
11. Inspect the coupon for fusion type defects. **Reference AWS D1.1 Structural Welding Code, for acceptance criteria.**

Inspection by instructor: _____	Instructors signature: _____
Date: _____	Student signature: _____

Bend Test Procedure For 1" Test Plate


Bend tests are used to determine the ductility and soundness of a weld joint. The test will allow the welder to determine if she or he has obtained fusion in the weld joint. Use the following procedure in preparing and bending your coupons.

1. Flush back up strip off of the plate at the flushing station.



2. Layout four 3/8" coupons and cut using the track burner. **Do Not Bend** coupons greater than 3/8 " thick it will damage the dies in the bending machine!


SHOP TEST
BEND TEST COUPON PREPERATION FOR SHOP TEST



TEST COUPONS SHALL BE FREE OF ALL DEFECTS SUCH AS UNDERCUT,
POROSITY, SLAG INCOMPLETE FUSION, AND OTHER DEFECTS PER AWS D1.1

Inch	MM
1/16"	1.6
1/8"	3.2
1/4"	6.4
1/2"	12.7
1"	25.4

Part No.	Required	Size(WxLxT)	S.I. Conversion

 Portland Community College Welding Technology			
Tolerance (Unless otherwise Specified)		WLD 141 Bend Test Layout	
Dimensional $\pm 1/16"$ Angle $\pm 5^\circ$		Size:	Gc No.
Drawn By: John Deering		Rev.	
Chk By:	Date: 5/22/05	Approve Date	Sheet

3. Allow coupon to air cool. **Do Not Quench!**
4. Grind coupon's smooth, ensuring grinding marks are going with the length of the coupon's and all edges are rounded.
5. Request permission from your instructor to use the bend test machine.
6. **CAUTION:** *Keep hands and fingers clear when operating equipment.*

Watts Bend Test Machine



7. Ensure guard is in the correct position. The coupons sometimes eject out of the end of the machine rapidly.


Guard



8. Place coupon in the machine taking care not to position your hands/fingers in the way. Locate weld in the center of the die. Bend one coupon (from each plate) to test the face and one to test the root.
9. Actuate the ram by the lever on top of machine and stand clear of the guard area where coupon will exit.

10. Inspect the convex surface of the bend specimen for fusion type defects.

Reference the AWS D1.1 Structural Welding Code for Acceptance Criteria for Bend Tests.



Four types of bend samples are shown above. Left to right are: face bend, face bend, root bend and a side bend



The bend samples shown above differ in the radius that they were bent. This is a requirement set forth by the code or standard that is being used.

E71T-1 Groove Weld (2G)

Project #6

Welding Sequence

E71T-1-- Root Pass

Single pass technique with slight weave to ensure the weld metal is fusing into both pieces of metal.

E71T-1—Fill

Use the split bead technique with stringer beads ensuring even fill.



E71T-1—Finish Beads

Use stringer bead technique keeping the electrode in the puddle at all times.



VT Criteria	Visual Inspection	Bend Tests
Reinforcement (0" -1/8")		Acceptable
Fillet Weld Size		
Undercut (1/32")		
Bead Contour (smooth)		
Penetration		Not Acceptable
Cracks (none)		
Arc Strikes (none)		
Fusion (complete)		
Porosity (none)		Grade Date

WLD 141
Horizontal Groove (2G)



Welding Procedure

1. Electrode — E71T-1
2. Diameter — 1/16"
3. Polarity — DCRP
4. Voltage — 24-26
5. Amperage — 200-220
6. Welding Position — Horizontal (2G)
7. Material — 1" Plate
8. Travel Angle (Drag) — 20°-30°
9. Work Angle — Varies
10. CO2 Shielding gas — 45 cfh

Inch	MM
1/16"	1.6
1/8"	3.2
1/4"	6.4
1/2"	12.7
1"	25.4

Part	No. Required	Size (WxHxL)	S.I. Conversion

Tolerance (Unless otherwise Specified)		WLD 141-06	
Dimensional ± 1/16" Angle ± 5°		Size:	Qc No.
Drawn By: John Deering		Approve	Date
Chk By: TANNER SCOTT		Date: 8/19/08	Sheet



Portland Community College
Welding Technology

E71T-1 Groove Weld (3G)

Project #7

Welding Sequence

E71T-1-- Root Pass

Single pass technique with slight weave to ensure the weld metal is fusing into both pieces of metal.

E71T-1—Fill

Use the split bead technique with stringer beads ensuring even fill.

E71T-1—Finish Beads

Use stringer bead technique keeping the electrode in the puddle at all times.



VT Criteria	Visual Inspection	Bend Tests
Reinforcement (0" -1/8")		Acceptable
Fillet Weld Size		
Undercut (1/32")		
Bead Contour (smooth)		
Penetration		Not Acceptable
Cracks (none)		
Arc Strikes (none)		
Fusion (complete)		
Porosity (none)		
		Grade Date

WLD 141

Groove Weld (3G) T-Joint

Welding Procedure

1. Electrode _____ E71T-1
2. Diameter _____ 1/16"
3. Polarity _____ DCRP
4. Voltage _____ 24-26
5. Amperage _____ 200-220
6. Welding Position _____ Vertical (3G)
7. Material _____ 1" Plate
8. Travel Angle (Drag) _____ 20°-30°
9. Work Angle _____ Varies
10. CO₂ Shielding gas _____ 45 cfh

Inch	MM
1/16"	1.6
1/8"	3.2
1/4"	6.4
1/2"	12.7
1"	25.4

Part	No. Required	Size (WxHxL)	S.I. Conversion

Portland Community College Welding Technology	
Tolerance (Unless otherwise Specified)	WLD 141-07
Dimensional ± 1/16" Angle ± 5°	Size: Qc No. Rev.
Drawn By: John Deering	Approve Date
Chk By:	Date: 10/01/03

E71T-1 T-Joint (4G)

Project #8

Welding Sequence

E71T-1-- Root Pass

Single pass technique with slight weave to ensure the weld metal is fusing into both pieces of metal.

E71T-1—Fill

Use the split bead technique with stringer beads ensuring even fill.




E71T-1—Finish Beads

Use stringer bead technique keeping the electrode in the puddle at all times.



VT Criteria	Visual Inspection	Bend Tests	
Reinforcement (0" -1/8")		Acceptable	
Fillet Weld Size			
Undercut (1/32")			
Bead Contour (smooth)			
Penetration		Not Acceptable	
Cracks (none)			
Arc Strikes (none)			
Fusion (complete)			
Porosity (none)		Grade	Date

WLD 141 Overhead Groove (4G)



Welding Procedure

1. Electrode _____ E71T-1
2. Diameter _____ 1/16"
3. Polarity _____ DCRP
4. Voltage _____ 24-26
5. Amperage _____ 200-220
6. Welding Position _____ Overhead (3G)
7. Material _____ 1" Plate
8. Travel Angle (Drag) _____ 20°-30°
9. Work Angle _____ Varies
10. CO₂ Shielding gas _____ 45 cfh

Inch	MM
1/16"	1.6
1/8"	3.2
1/4"	6.4
1/2"	12.7
1"	25.4

Part	No. Required	Size (WxHxL)	S.I. Conversion



Portland Community College
Welding Technology

Tolerance (Unless otherwise Specified)
Dimensional $\pm 1/16"$ Angle $\pm 5^\circ$

Drawn By: John Deering

Chk By: _____

Date: 10/01/03

WLD 141-08

Size: _____

Qc No. _____

Rev. _____

Approve _____

Date _____

Sheet _____

Sheet _____

Final Exam

Part One

This portion of the final exam is a closed book test. Consult with your instructor to determine items that you may need to review. Once you determine that you are ready for the exam, request it from your instructor. Complete the exam and write all answers on the answer sheet provided. Once completed, return the exam to your instructor for grading.

Study Guide

Safety

- Electrical**
- Oxyacetylene**

Machine Components

- Power Source**
- Wire Feeder**
- Gun and Ground Clamps**
- Polarity**
- Gas Cylinders**

Metal Transfer

- Globular**

Gases

- Mixed gases**

Wire

- AWS Classification System**

FCAW Vocabulary

Weld Defect Vocabulary


Part Two


This portion of the exam is a practical test where you will fabricate and weld a weldment from a “blue print.” The evaluation of this portion of the exam will be based on the *Traveler*.



WLD 141 Practical Final

Note:
 All Keyholes 3/4" Radius
 All material thickness 1/2"
 Use iron worker to punch holes.
 Make all welds in the flat and horizontal position.



		Portland Community College Welding Technology	
Part	No. Required	Size (WxHxL)	S.I. Conversion
		Tolerance (Unless otherwise Specified)	WLD 141—Practical Final
		Dimensional $\pm 1/16"$ Angle $\pm 5'$	Size: Qc No. Rev.
		Drawn By: John Deering	Approve Date
		Chk By:	Date: 10/01/03
			Sheet

Grading Traveler for the WLD 141 Practical Exam

**Hold Points are mandatory points in the fabrication process, which require the inspector to check your work.
You will have the following hold points that you instructor will check**

<i>Points Possible</i>	<i>Hold Points</i>	Instructor's Evaluation
5 points	Blueprint Interpretation and Material Cut List 5 points = 0 errors, all parts labeled and sized correctly 3 points = 1 error in part sizing and/or identification 2 points = 2 errors or more rework required (max points)	
10 points	Material Layout and Cutting (Tolerances +/- 1/16") 10 points Layout and cutting to +/-1/16" Smoothness of cut edge to 1/32" 7 points Layout and cutting to +/- 1/8" Smoothness of cut edge to 1/16" 5 points (Rework required max points) Layout and cutting to +/-3/16" Smoothness of cut edge to 3/32"	
10 points	Fit-up and Tack weld (Tolerances +/- 1/16") 10 points Tolerances +/- 1/16" Straight and square to +/-1/16" 7 Points Tolerances +/- 1/8" Straight and square to +/-1/8" 5 Points (Rework required - Max points) Tolerances +/- 3/16" Straight and square to +/-3/16"	
15 points	Weld Quality Subtract 1 point for each weld discontinuity, incorrect weld size and incorrect spacing sequence.	
<i>35 points</i>	<i>Minimum points acceptable. This equates to the minimum AWS D1.1 Code requirements.</i>	
	Total Points	/40

Final Grades - WLD 141

Name: _____ Instructor: _____ Date: _____

Welding Projects = 40%

Out of 10	Out of 10	Out of
Out of 10	Out of 10	Out of
Out of 10	Out of	Out of
Out of 10	Out of	Out of
Out of 10	Out of	Out of
Out of 10	Out of	Out of
A Total Project pts. _____ / Total pts. Possible _____ X 40 = _____ %		

Quizzes = 20%

Out of	Out of	Out of
Out of	Out of	Out of
Out of	Out of	Out of
B Total Project pts. _____ / Total pts. Possible _____ X 20 = _____ %		

Attendance = 10% The following attributes will be assessed - attendance, attitude, time management, team work, interpersonal skills, etc.. Daily points (there are no excused absences, hence no points earned for days missed) 3 pts = present and working for the entire shift; 2 pts = late; 1 pt = late and left early; 0 pts = no show.

Out of	Out of	Out of	Out of	Out of	Out of
Out of	Out of	Out of	Out of	Out of	Out of
Out of	Out of	Out of	Out of	Out of	Out of
D Total pts. earned _____ / Total pts. Possible _____ X 10 = _____ %					

Final Exams 30%

Written Exam	Out of
Practical Exam	Out of
E Total Project pts. _____ / Total pts. Possible _____ X 30 = _____ %	
Add Lines A + B + C + D + E. This will give you your Final Grade TOTAL % _____	
FINAL GRADE _____	